



7. east wall: the building is supported with a series of strongbacks. The one in the middle of the wall is located on the mid wall vertical log



8. east wall, detail of upper rear corner, showing the typical steel strap and galvanized gutter. The squared log which is fitted into the soffit shows clearly